3ʳᵈ ENCWG Meeting
Wollongong, Australia (16 - 18 April 2018)
Actions from ENCWG2 Meeting

No	Item	Action	Who	Status
colspan		**ENCWG2 – Genoa, Italy (20-22 March 2017)**		
		Action Items		
01	3	[Action ENCWG1/02] IHO Check Dataset – Instructions check ECDIS legend for edition number. Write guidance paper for OEMs to add to user guides.	Chair	Ongoing
02	3	[Action ENCWG1/04] S-52 PL 10.1.7 Limit of ENC Coverage: Non-IHO data on the display – Reword to always display over non-ENC data. Draft new section – for PL Ed 4.1.	Chair	On Hold
03	3	[Action ENCWG1/06] S-52 PL UDWHAZ05 Isolated danger symbol in unsurveyed areas – Add LNDARE and UNSARE into UDWHAZ05 – For Edition 4.1 of the PL.	EM(?)	On Hold
04	3	[Action ENCWG1/08] S-52 PL Appendix D – Look-up Table Listing for Object of Type 'L' – Fix MAGVAR Line to use point SY(MAGVAR01) which does not have an offset – For Edition 4.1 of the PL.	Chair	On Hold
05	3	[Action ENCWG1/10] S-52 PL LIGHTS06 CSP – Depending on outcome of testing of new rules for displaying omnidirectional lights, update CSP – For Edition 4.1 of the PL.	EM(?)	On Hold
06	3	[Action ENCWG1/11] S-64 – Depending on outcome of testing of new rules for displaying omnidirectional lights, new screen shots for all tests that have omnidirectional lights – For Edition 3.1 of the S-64.	HP	On Hold
07	3	[Action ENCWG1/12] S-52 PL UDWHAZ05 CSP – Update UDWHAZ05 CSP to compare the feature VALSOU with the "largest value of either the 'Safety Contour' and the 'Safety Depth'" - UML edits Safety Depth – For Edition 4.1 of the PL.	EM(?)	On Hold
08	3	[Action ENCWG1/13] Test display based on new rules in UDWHAZ05 CSP.	OEMs	Ongoing
09	3	[Action ENCWG1/15] Extended use of NEWOBJ for V-AIS (Wind Farms) – BSH to work with NCWG on encoding.	BSH	Ongoing
10	3	[Action ENCWG1/16] Object names. Change LUTs to add OBJNAM for LNDMRK category of landmark Wind Turbine and OSPARE. BSH to investigate with an OEM the best fit for the text label alteration for text instructions HJUST, VJUST, XOFFS, YOFFS in the LUTs– result to be circulated to the ENCWG (NOTE: The solution should not overly clutter the ECDIS screen) - For Edition 4.1 of the PL.	Chair/BSH	On Hold
11	3	[Action ENCWG1/17] S-64 – Modify ENC test dataset to add LNDMRK – Wind Turbine with two LIGHTS features.	HP	Ongoing
12	5.1	Invite CIRM to review the S-52 and S-64 clarifications and provide any comments to the Chair by 30 May. Compile a consolidated list of new changes to the PL. Draft an IHO letter to OEMs requesting comments by 31 April. (Document publish date is to be 1 June 17).	Chair	In Progress
13	5.2	Request HSSC chair to obtain HSSC endorsement of UOC	Chair/	Completed

		Revision 4.1.0 by correspondence – for submission to the IHO Council.	IHO Sec.	
14	5.3	Investigate what funds could be made available for the development of test data sets for S-58 critical errors. If funds available, seek approval and place contract for their development.	Chair/IHO Sec.	In Progress
15	5.3	Ensure that the items identified during the S-58 breakout group work are included in MS responses to CL21 (requesting approval of S-58), so that they can be taken into account before the final document is released.	DK and other MS	Completed
16	5.3	Prepare final version of S-58 Edition 6.0.0 based on MS responses to CL 21/2017 for publication.	IHO Sec.	Completed
17	5.4	Redesign the S-62 Producer Code database to cater for S-100 requirements, and integrate it into the new IHO Registry server application. (NOTE: Also S-100WG action.)	IHO Sec./ KHOA	
18	5.5	Review the new version of S-63 (Edition 1.2), in particular Annex C, and report any issues or comments to the ENCWG Chair.	All	
19	5.6	Review new Clarification version (3.0.2) of S-64 and associated test datasets and provide any comments to JP before 01 May 2017.	All/OEMs	Time Expired
20	5.6	Remove the PlesLib Edition 3.4 Check Data Set from the IHO Website after 31 August 2017.	IHO Sec.	Pending
21	5.7	ENCWG members to ensure that their home offices return their CL voting papers for the approval of the new Revision 2.1.0 of S-65.	All	Time Expired
22	5.8	Complete the S-66 document to include the ENCWG consolidated comments and the work of the S-66 Project Team, and produce an Edition 1.1.0 for consideration by the 1st IHO Council meeting in October 2017 (subject to prior endorsement by the HSSC by correspondence).	IHO Sec.	Completed
23	5.9	Amend the *Information on ECDIS Software* page of the IHO web site to remove manufacture contact information.	IHO Sec.	
24	5.9	Restructure the IHO web pages to separate the content for the current ENC standards and resources, and the S-100 standards and resources development work. (NOTE: Also an S-100WG action).	Chair/ IHO Sec.	
25	5.9	Produce text to advise Port State Inspectors (and others) on what will happen on the 31 August, when the PresLib 3.4 Check Data Set will be removed from the IHO web site, and informing on the ECDIS Chart 1 check that may be used to check compliance to S-52 Edition 4.0.	S-52 Sub-WG	Completed (?)
26	6.1	Amend S-64 graphics to remove any displayed "()" or "(1)" values for signal group.	HP	
27	6.1	Amend S-52 PresLib clause 10.6.3 to clarify that a displayed light description can be shown with or without a space between the light characteristic and the light colour	Chair/ IHO Sec.	Completed
28	6.2	Report to the next HSSC meeting on the outcome of the bENC discussion.	Chair	
29	6.3	Call for WG volunteers to (a) lead, and (b) participate in, the "ENC Best Practices" Sub-WG.	Chair	

30	6.3	Develop guidance for MS on including T&P information on ENCs.	Chair/ NCWG/ Sub-WG	
31	6.3	Report on the outcome of the T&P sub group to the NCWG (see also Action HSSC8/28).	MH	
32	6.3	Request feedback from ENC production system manufacturers on whether it is possible to produce database ENC Updates (for T&Ps) without having an impact on the corresponding paper charts.	Chair	
33	6.5	ENCWG members are requested to inform their offices of the ECDIS APT guidelines and consider endorsing them when presented by CIRM.	All	
34	6.7	Issue a CL advising MS on the importance of populating meaningful values for CATZOC and requesting them to especially review those areas that are designated as "unassessed". Sub-WG to include this advice in guidance document.	Chair/ IHO Sec./ Sub-WG	
35	7.4A	Provide feedback on issues raised by Port State Control (Action HSSC8/56) to the HSSC9 meeting, as part of the ENCWG report.	Chair	
36	7.4E	Correspondence Sub-WG to carry out study on how to improvement of ENCs display on ECDIS. For consideration at 2018 ENCWG meeting.	Sub-WG (CM Lead)	